

# Uniden UBCD996T Firmware Revision Notes 1.01.05

## ***What is Changed by This Update?***

This firmware update makes the following improvements to your UBCD996T scanner.

- Change UHF Air Channel Step from 50Khz to 25 KHz step.
- Add WACN to P25 system info display (along with SYS ID).
- P25 audio performance improvement.
- Change waiting message in MENU, "Wait please --> Please wait"

## ***Applying the Update***

Before applying the update, you need to download the files from the Uniden Australia Pty. Ltd. web site. Navigate to [http://www.uniden.com.au/AUSTRALIA/p\\_ubcd996t\\_index.asp](http://www.uniden.com.au/AUSTRALIA/p_ubcd996t_index.asp) Then, download:

- **UBCD996T\_V1\_01\_05.zip** – this is the compressed scanner firmware file
- **Install\_UBC\_VUP\_v1.1.0.2.exe** – this is the application that applies the new firmware to your scanner

1. Navigate to the location where you saved the above files and unzip the first files (it will be UBCD996T\_V1\_01\_05.scn).
2. Run the "Install\_UBC\_VUP\_v1.1.0.2.exe" program. This installs the firmware version updater on your PC. (**Note:** If you have previously installed this version, you do not need to install it again.)
3. Run the installed application in the "Guided mode." When prompted, select the scanner firmware file you downloaded.

## **Update Troubleshooting**

Follow these tips to troubleshoot any update problem you encounter:

- When prompted, be sure to turn off the scanner and hold down both the L/O and 6 buttons while turning ON the unit. The backlight should come on and remain on until the end of the update.
- If an error occurs during the update, simply repeat all steps, *including removing power, holding down L/O and 6, and plugging in AC power*. Even if the backlight is already on, you need to repeat this step if you restart the update.
- Almost all update error messages are caused by:
  - Incorrect COM port selection: Be sure you have selected the COM port that the scanner is plugged into.
  - COM port software conflicts: No other software can be running that uses the COM port. Be sure to close UASD and any other scanner control software. Also, if you have ever used a PDA with this PC, there is probably synchronization software running all the time that takes over the COM port. You can usually stop that software by right-clicking on its icon in the lower right side of your PC screen, then selecting “Quit” or “Exit.”